

# WELDING POSITIONS

Flat



1F



1G

Horizontal



2F



2G

Vertical



3F



3G

Overhead



4F



4G