



# TYPES OF WELDING JOINTS


## Butt Joints



Closed Square




Open Square



Single Bevel




Double Bevel



Single V




Double V




Single J



Double J




Single U



Double U


## Edge Joints



Square Groove

Bevel Groove


V Groove




J Groove

U Groove


## Corner Joints




Flush




Open Corner




Inside Bevel




Outside Bevel




Outside J Groove



Inside J Groove




U Groove




V Groove


## Lap Joints




## Tee Joints




Plain Tee




Single Bevel



Double Bevel



Single J



Double J