



Advance Manufacturing Training Program

WELDING

To: Welding Students

Subj: Welding Safety and Shop Requirements List

The Advance Manufacturing Training Program works hard to provide a safe and clean welding lab for all our students. The program will provide some basic welding personal protection equipment, but it is the responsibility of each student to provide and maintain the following items. Items that are marked as optional are listed to improve your experience in the lab, all other items are required. No student will operate in the shop without the required protection.

Provided by Program:

Leather Gloves

Welders Cap

Eye Protection

Welding Jacket

Hearing Protection – Ear Plugs

Student Requirements for Welding Shop:

Welding Hood – Minimum 10 Shade protection.

Leather Work Boots

Heavy Pants – Jeans, Duck (No rips, tears, grease or flammable materials)

Cotton Shirt – Short or Long Sleeve

Combination Lock for Locker

Recommendations: Optional

Auto-Darkening Welding Hood

Flashlight

Three-way Plug Splitter

Cheap Shop Glasses (If you require glasses for vision)

The items will be discussed in class. If you have any questions or concerns about equipment and/or requirements, please contact the instructor for additional information.